

Address: Alameda Dr. Carlos
D'Assumpção, 336-342
Centro Comercial Cheng
Feng, 18^o andar, Macau

Tel: (853) 28511213

FAX: (853) 28338089

AFTN: VMMCYAYI

E-mail: aacm@aacm.gov.mo

澳門特別行政區
REGIÃO ADMINISTRATIVA ESPECIAL DE MACAU



民航局

AUTORIDADE DE AVIAÇÃO CIVIL
CIVIL AVIATION AUTHORITY

AERONAUTICAL INFORMATION SERVICE

AIP Supplement

No. 04/26

Date: 06 Oct 2026

SUBJECT: CLOSURE OF RUNWAY AT MACAU INTERNATIONAL AIRPORT (VMMC) **DUE TO CONSTRUCTION WORK OF AIRPORT EXPANSION**

1 Introduction

- 1.1. Macau International Airport (VMMC) will undertake nightly closure of RWY 16/34 due to land reclamation and new taxiway construction works on the western side of the runway.

2 Runway Closure Period

- 2.1. RWY 16/34 will be closed nightly from 1600 UTC to 2359 UTC during the following periods:

Dates of Closure (UTC)	Closure Time (UTC)	Reopening Time (UTC)	Duration of Closure
24 Oct 2026 - 28 Jan 2027	16:00	00:00 +1	8 hours
13 Feb 2027 - 17 Jan 2028	16:00	00:00 +1	8 hours
01 Feb 2028 - 04 Feb 2029	16:00	00:00 +1	8 hours
20 Feb 2029 - 26 Oct 2029	16:00	00:00 +1	8 hours

3 Limitations and Operational Procedures

- 3.1. Closure times will be strictly adhered to, and the RWY 16/34 will be unavailable for all air traffic during the specified closure periods.
- 3.2. Arriving aircraft must be fully established on final approach sufficiently in advance to ensure landing prior to the closure time.
- 3.3. Departing aircraft must be ready for immediate taxi and line-up no later than a reasonable time prior to the closure.
- 3.4. RWY 16/34 **cannot** be reopened for technical stops, diversions, or emergencies during closure periods.
- 3.5. Macau International Airport (VMMC) shall not be filed as an alternate aerodrome in flight plans for flights where the estimated time of arrival coincides with a scheduled closure period.

- 3.6. All construction personnel, vehicles, and equipment will be cleared from the runway and runway strip areas when the runway is reopened for operation.
- 3.7. Runway closure schedule may be revised in the event of forecast or actual adverse weather conditions or other extenuating circumstances.

4 Validity and Changes

- 4.1. This AIP Supplement is effective from the date of publication and remains in force until 00:00 UTC on 27 October 2029, or until cancelled/superseded by subsequent publication or NOTAM.
- 4.2. Any change to the contents of this AIP Supplement or the runway closure schedule will be promulgated by NOTAM.

5 This AIP SUP supersedes AIP SUP No. 01/26.

6 Contact information

- 6.1. For further information or queries:

Unit: Airport Operations Service, Macau International Airport

Tel: +853 8898 2501

E-Mail: airportdutymanager@macau-airport.com