

Address: Alameda Dr. Carlos
D'Assumpção, 336-342
Centro Comercial Cheng
Feng, 18° andar, Macau

Tel: (853) 28511213

FAX: (853) 28338089

AFTN: VMMCYAYI

E-mail: aacm@aacm.gov.mo



AIP Supplement

No. 03/26
Date: 20 Aug 2026

IMPORTANT: This AIP SUP provides advance notice of a major temporary facility outage. NOTAMs will be published in conjunction and take precedence

SUBJECT: TEMPORARY SERVICE OUTAGE OF RWY 34 ILS AT MACAU INTERNATIONAL AIRPORT (VMMC) DUE TO RECONSTRUCTION WORK OF CNS PROJECT

1. Introduction

1.1. Macau International Airport (VMMC) will undertake reconstruction of RWY 34 ILS as part of the CNS project.

2. Planned Service Outage Period

2.1. RWY 34 ILS is planned to be temporary shut down during the following periods:

System	Service Outage Start (UTC)	Service Outage End (UTC)	Duration of Outage
RWY 34 ILS 'MCN'	10 Sep 2026 at 00:00	1 Feb 2027 at 00:00	145 days

2.2. The actual service outage schedule, including any short-notice adjustments, will be promulgated by NOTAM.

3. Limitations and Operational Procedures

3.1. Service outage times are planned adhered to, and the RWY 34 ILS will be unavailable for all air traffic operations during the specified outage periods.

3.2. During the service outage of RWY 34 ILS, the following instrument flight procedures are affected:

Affected Flight Procedures	Details
ILS z RWY 34 RNAV(GNSS) ILS y RWY 34 ILS x RWY 34	Not available. Use RNP RWY 34 or VOR/DME RWY 34.

4. Validity and Changes

4.1. This AIP Supplement is effective from the date of publication and remains in force until 00:00 UTC on 1 February 2027, or until cancelled/superseded by subsequent publication or NOTAM.

4.2. Any changes to the contents of this AIP Supplement or to the service outage schedule will be promulgated by NOTAM.

5. Contact information

5.1. For further information or queries:

Unit: Airport Operations Service, Macau International Airport

Tel: +853 8898 2501

E-Mail: airportdutymanager@macau-airport.com