

Phone:(853) 2851 1213

Fax: (853) 2833 8089

AFTN: VMMCYAYI

E-mail: aacm@aacm.gov.mo



AERONAUTICAL INFORMATION SERVICE

**NOTAM  
SUMMARY**

01 JAN 18

The following NOTAM were still in force at 0001 (UTC) on 01 JAN 18. NOTAM not included have either been canceled, or superseded by AIP Supplement or incorporated in AIP-Macao.

## NOTAM SUMMARY

- A0113/16 A) VMMC B) 1605260417 C) PERM  
E) WHENEVER ZUH IS U/S, ARRIVING ACFT CONDUCTING MISSED APCH OF LLZ/DME X RWY16 RNAV (GNSS) WILL EXPECT RADAR VECTOR AFTER INDUS. REF AIP AD2-VMMC-71D.
- A0132/16 A) VMMC B) 1605310925 C) PERM  
E) ARRIVING ACFT USING LLZ/DME Z RWY16 OR LLZ/DME Y RWY16, VIA STAR BIGRO 1A EXPECT RADAR VECTOR FROM GURIN TO IAF, VIA STAR CHALI 5B OR SMT 5B EXPECT RADAR VECTOR FROM INDUS TO IAF. REF AIP AD2-VMMC-68A, 68C,71 AND 71A.
- A0133/16 A) VMMC B) 1605310928 C) PERM  
E) ARRIVING ACFT ON STAR BIGRO 8A TO LLZ/DME X RWY16 RNAV(GNSS) OR RNAV(GNSS) RWY16, EXPECT RADAR VECTOR FROM GURIN TO IAF. REF AIP AD2-VMMC-67, 71B AND 71D.
- A0221/17 A) VMMC B) 1801040000 C) 1801172359  
E) TRIGGER NOTAM - PERM AIRAC AIP AMDT 02/17 WEF 04 JAN 2018. IMPLEMENTATION OF THE NEW MAGNETIC VARIATION 3 DEGREE W (ROUNDED).
- A0233/17 A) VMMC B) 1801040000 C) 1801172359  
E) PERM AIP AMDT 33 WEF 04 JAN 2018 TO CORRECT OPS SIGNIFICANT PAGES OF PERM AIRAC AIP AMDT 02/17. DUE TO EXPECT DELAY OF POSTAL SERVICE IN FESTIVAL, PLEASE REFER PERM AIP AMDT 33 AT [HTTP://WWW.AACM.GOV.MO/IMAGES/DOWNLOAD1/201712158082530.PDF](http://www.aacm.gov.mo/images/download1/201712158082530.pdf)
- A0234/17 A) VMMC B) 1802010000 C) 1802142359  
E) AIRAC EFFECTIVE DATE 1 FEB 2018 NIL.
- A0235/17 A) VMMC B) 1712290924 C) 1801312359 EST  
E) REFERRING TO AIP GEN 3.6-1 TABLE 3.6.3, SAR VESSEL IN THE VICINITY OF AIRPORT NOT AVAILABLE DUE TO MAINTENANCE.  
SAR VESSEL 'ILHAVER II' AVAILABLE AT 2212.53N 11332.38E WITH 2 LIFE RAFTS FOR 20 PERSONS PER EACH RAFT.  
SAR VESSEL 'NAM VAN' AVAILABLE AT 2211.87N 11333.66E WITH CAPACITY MAXIMUM 70 PERSONS PLUS WITH 4 LIFE RAFTS FOR 50 PERSONS PER EACH RAFT.
- A0236/17 A) VMMC B) 1712290930 C) 1801312359 EST  
E) REFERRING TO AIP GEN 3.6-1 TABLE 3.6.3, 2 BOATS FOR RESCUE IN THE VICINITY OF AIRPORT NOT AVAILABLE DUE TO MAINTENANCE.

- A0237/17 A) VMMC B) 1712290933 C) 1801312359 EST  
 E) REFERRING TO AIP GEN 3.6-1, TABLE 3.6.3, 2 BOATS FOR FIRE FIGHTING  
 IN THE VICINITY OF AIRPORT NOT AVAILABLE DUE TO MAINTENANCE.
- A0238/17 A) VMMC B) 1801022000 C) 1801302200  
 D) TUE THU SUN 2000-2200  
 E) RWY16/34 CLOSED DUE TO MAINTENANCE.
- A0239/17 A) VMMC B) 1712290938 C) 1803312359  
 E) AIRCRAFT PARKING STAND G15 CLOSED DUE TO WIP.

### **CHECK LIST**

NOTAM TRANSFERRED TO AIP SUPPLEMENT : NIL  
 NOTAM TRANSFERRED TO AIP : NIL

LATEST AIP REGULAR AMENDMENT ISSUED : **33 (04 JAN 2018)**  
 LATEST AIP AIRAC AMENDMENT ISSUED : 02/17 (23 NOV 2017 IMPLEMENTATION ON 04 JAN 2018)  
 LATEST AIP SUPPLEMENT : 01/16 (17 MAR 2016 implementation informed by NOTAM)  
 LATEST AIC Series A : **02/18 (01 JAN 2018)**  
 LATEST AIC Series B : **01/18 (01 JAN 2018)**

CURRENT AIP SUPPLEMENT IN FORCE : NIL  
 CURRENT AIC Series A IN FORCE : 01/95, 02/95, 03/95, 06/96, 03/98, 03/10, 03/11, 04/12, 04/13,  
 03/14, 04/14, 06/14, 04/16, 03/17, **01/18, 02/18**

CURRENT AIC Series B IN FORCE : 02/96, 01/98, 03/98, 02/00, 11/01, 15/02, 03/09, 10/11, 11/11,  
 01/12, 15/12, 02/15, 03/15, 04/15, 05/15, 08/17, 09/17, 10/17,  
 11/17, 12/17, 13/17, 14/17, 15/17, 16/17, 17/17, **01/18**