

Phone:(853) 2851 1213

Fax: (853) 2833 8089

AFTN: VMMCYAYI

E-mail:aacm@aacm.gov.mo



AERONAUTICAL INFORMATION SERVICE

**NOTAM
SUMMARY**
01 SEP 23

The following NOTAM were still in force at 0001 (UTC) on 01 SEP 23. NOTAM not included have either been canceled, or superseded by AIP Supplement or incorporated in AIP-Macao.

NOTAM SUMMARY

- A0230/23 A) VMMC B) 2306301021 C) 2309302359
E) LOC ILS RWY 34 UNUSABLE BEYOND 20 DEG LEFT OF COURSE.
- A0278/23 A) VMMC B) 2310050000 C) 2310182359
E) TRIGGER NOTAM - PERM AIRAC AIP AMDT 01/23 WEF 05 OCT 2023. RENAME OF STANDARD INSTRUMENT DEPARTURE PROCEDURE (SID) DUE TO EXISTING WAYPOINT 'GLN' REPLACED BY 'GUBLO'.
- A0280/23 A) VMMC B) 2307311013 C) 2309301400
D) DAILY 1100-1400
E) MIXED LIGHTS DISPLAY WILL TAKE PLACE WI COORD:
221249N 1133642E
221329N 1133739E
221249N 1133807E
221207N 1133712E
(FROM 4NM TO 5NM NORTHEAST OF ARP.)
ILLUMINATION RANGE OF LIGHT BEAM WITHIN A DISTANCE OF 300M AND LASER BEAM WITH HORIZONTAL DISTANCE OF 200M.
F) SFC G) 300M AMSL
- A0299/23 A) VMMC B) 2308140000 C) 2310312359
E) AIRCRAFT STAND G8 CLOSED DUE TO WIP.
- A0300/23 A) VMMC B) 2308150000 C) 2310312359
E) COLOR-CODED AIRCRAFT PUSHBACK PROCEDURES, COLOR CODE GREEN FOR PUSHBACK OF AIRCRAFT WITH WINGSPAN LESS THAN 36M SHALL BE TOWED TO BREAKAWAY POINT 2. REF AIP PAGE AD2-VMMC-14 PARA.8.7.
- A0301/23 A) VMMC B) 2308150000 C) 2310312359
E) PUSH BACK OF AIRCRAFT WITH APU PROBLEM ON B07 OR B10 OR B10L OR B10R SHALL FOLLOW COLOR-CODED AIRCRAFT PUSH BACK PROCEDURES, COLOR CODE PINK FOR PUSH BACK OF AIRCRAFT. REF AIP PAGE AD2-VMMC-14 PARA.8.7.
- A0302/23 A) VMMC B) 2309091300 C) 2310071400
D) SEP 09 16 23 1300-1400, OCT 01 07 1300-1400
E) FIREWORK WILL TAKE PLACE WITHIN:
250M RADIUS CENTRED ON 221036N 1133308E (600M SOUTH FROM MACAU TOURIST TOWER)
F) GND G) 300M AMSL
- A0303/23 A) VMMC B) 2308171029 C) 2310312359
E) PUSH BACK OF AIRCRAFT WITH APU PROBLEM ON B5 OR B8 SHALL FOLLOW COLOR-CODED AIRCRAFT PUSH BACK PROCEDURES, COLOR CODE PINK FOR PUSH BACK OF AIRCRAFT. REF AIP PAGE AD2-VMMC-14 PARA.8.7.

A0310/23 A) VMMC B) 2308301013 C) 2309302359 EST
 E) REFERRING TO AIP GEN 3.6.1, TABLE 3.6.3, AND AD 2.6, 3 BOATS USED
 FOR RESCUE AND FIRE FIGHTING IN THE VICINITY OF AIRPORT ARE
 AVAILABLE, EACH BOAT EQUIPPED WITH 2 LIFE RAFTS WITH A CAPACITY OF 38
 PERSONS EACH.

SAR VESSELS OF MARINE AND WATER BUREAU AVAILABLE AT 2212.25N
 11332.24E WITH 2 LIFE RAFTS FOR 20 PERSONS PER EACH RAFT, AND AT
 2212.55N 11332.41E WITH CAPACITY 43 PERSONS PLUS 4 LIFE RAFTS FOR 50
 PERSONS PER EACH RAFT.

A0311/23 A) VMMC B) 2308301019 C) 2309022300
 D) DAILY 1800-2300
 E) AD NOT AVBL FOR ALTN DUE TO MAINTENANCE.

A0312/23 A) VMMC B) 2309032000 C) 2309282200
 D) TUE THU SUN 2000-2200
 E) RWY 16/34 CLOSED DUE TO MAINTENANCE.

CHECK LIST

NOTAM TRANSFERRED TO AIP SUPPLEMENT : NIL
 NOTAM TRANSFERRED TO AIP : NIL

LATEST AIP REGULAR AMENDMENT ISSUED : 45 (13 JUL 2023)
 LATEST AIP AIRAC AMENDMENT ISSUED : 01/23 (27 JUL 2023 IMPLEMENTATION ON 05 OCT 2023)
 LATEST AIP SUPPLEMENT : 01/22 (01 DEC 2022)
 LATEST AIC Series A : 03/23 (27 APR 2023)
 LATEST AIC Series B : 07/23 (06 JUN 2023)

CURRENT AIP SUPPLEMENT IN FORCE : 01/22
 CURRENT AIC Series A IN FORCE : 01/95, 02/95, 03/95, 06/96, 03/98, 03/10, 03/11, 04/12, 04/13,
 03/14, 04/14, 06/14, 05/19, 03/21, 03/22, 04/22, 01/23, 02/23,
 03/23

CURRENT AIC Series B IN FORCE : 02/96, 03/98, 02/00, 03/09, 10/11, 11/11, 01/12, 04/15, 05/15,
 08/17, 09/17, 10/17, 11/17, 12/17, 02/19, 03/19, 04/20, 03/21,
 08/21, 08/22, 01/23, 02/23, 03/23, 04/23, 05/23, 06/23, 07/23